



THORNDOWN

PEELABLE GLASS PAINT APPLICATION ADVICE

Please do not paint this on to your greenhouse unless weather conditions are consistently warm and/or dry with a strong sun.

When painting externally it is always recommended to make sure no rain is forecast within 24 hours of application. When painting glass paint onto glass or plastic materials this is even more essential, as the paint coating has to bond to a slippery surface.

Do not apply when night time temperatures are cold/freezing and humidity and condensation levels are high overnight and in the morning.

These poor night conditions will negatively impact on the drying process and although the coating will appear dry and be touch dry, it will not cure and bond to the glass properly. Painting in the morning gives the coating more chance of drying.

If the paint hasn't had enough time to dry and bond completely, any rain can get under the coating causing slippage, or break it down, and/or wash it off.

For best results apply with a roller using a foam sleeve.

If you have any questions please visit the website www.thorndown.co.uk where there is lots of advice and information, or email us on studio@thorndown.co.uk

Many thanks,
Thorndown Team

Thorndown Limited, Wells Road Trading Estate, Glastonbury, Somerset, BA6 9AG, United Kingdom

Tel 0800 023 5654 studio@thorndown.co.uk

Thorndown Limited registered in England and Wales, Bishopbrook, Cathedral Avenue, Wells, Somerset, BA5 1FD, No. 10569774

PEELABLE GLASS PAINT REMOVAL ADVICE

When it's time to remove the Peelable Glass Paint coating, just pick at a corner to bring up a piece of the coating, hold between your fingers and peel. The whole coating should come off in one sheet.

If the coating is thin and/or dried out during hot weather, dampen thoroughly with water to restore the elasticity of the coating, leave for about 10-15 minutes then peel off.

Drying out can happen if left on for a long time over a long season and polycarbonate and acetate/plastic materials can be more prone than glass.

Alternatively if you have any leftover Peelable Glass Paint, apply another coating on top, leave to dry for 24-48 hours so it bonds to the old coating, then peel all coatings off in one go.

If the coating is thin and patchy such as with small stencils, then it may be easier to remove with a paint scraper. Paint scrapers aren't recommended on plastics.

Structural integrity of the coating is essential for it being able to peel off.

You can view a raft of videos by visiting <https://thorndown.co.uk/projects/thorndown-paint-videos/#removal> to help you see how easy removal is with tips and advice.